


500

Cable system



* Cable (4) must be used when battery replaces the power supply.



1. Car battery cable
 Part No 571 125 140.
 Weight 0.2 kg 0.4 lbs

2. Battery cable
 Part No 571 136 750.
 Weight 0.1 kg 0.2 lbs

3. Cable Geodimeter-Geodat
 Part No 571 136 752.
 Weight 0.1 kg 0.2 lbs

4. Cable Geodimeter-Battery-Geodat
 Part No 571 136 754.
 Weight 0.1 kg 0.2 lbs

5. Cable Geodimeter-Battery-Computer
 Part No 571 136 756.
 Weight 0.1 kg 0.2 lbs

6. Cable Geodat/Control unit-Computer with power supply 220V
 Part No 571 136 874.
 Weight 0.4 kg 0.9 lbs

Cable Geodat/Control unit-Computer with power supply 115V
 Part No 571 136 876.
 Weight 0.4 kg 0.9 lbs

Cable Geodat/Control unit-Computer with power supply 230V
 Part No 571 136 908.
 Weight 0.4 kg 0.9 lbs

7. Cable Geodimeter-Battery-Radio
 Part No 571 202 214.
 Weight 0.1 kg 0.2 lbs

8. Cable for new external battery
571 204 270
 Part No 571 208 032.
 Weight 0.1 kg 0.2 lbs